

# **Professional Series Mobile Firmware R05.05.17 Customer Release Notes**

This release of radio firmware supports ALL models/bands of the Professional Series Mobile Radios. For any questions, please contact Customer Resources at 1-800-927-2744.

## **I. Enhancements**

None

## **II. Firmware Corrections**

### **Item #1: Quik Call II Alert tones cause unmute delay**

For mobile firmware versions R05.05.10, R05.05.12 and R05.05.15, following the receipt of a matching QCII two-tone sequence, the generated alert tones will delay the speaker unmute for the received audio.

This new firmware ensures that the speaker is unmuted for full receive audio.

## **III. Known Issues**

### **Item #1: Priority scan does not operate correctly with “Off Hook suspends Non-priority Scan”**

In specific operating scenarios, the radio will not scan detect priority 1 or priority 2 channel activity when the microphone is off the HUB and “Off Hook suspends Non-priority Scan” is active. The radio may also fail to revert to the selected channel after loss of carrier on the priority 1 or priority 2 channel.

This issue will be resolved in the next Professional Series Mobile Firmware release.

MOTOROLA and the Stylized M Logo are registered in the U.S. Patent & Trademark Office.  
All other product or service names are the property of their respective owners.  
© Motorola, Inc. 2005.